

Short description

The ESA1 accessories are necessary for the use of the ESA1 set. Among others the following parts are included: laboratory cable, measurement cable, measurement lines, connecting terminals, a foam block, a DC cable, and a plug-in power supply.