

Short description

The E2 Accessories are necessary for the use of the E2 set. Among others the following parts are included: micro-kleps, alligator clips, generator cables, measurement lines, adapter sockets, enamelled copper wire.